

Corrective Maintenance jobs either not taken on, not completed, were deferred or cancelled during the maintenance availability, including those identified but not completed during the MA.

Job Number	Job Title	Reason for deferral or non-completion (See legend below)										Additional comments	Risk Assessment (Safety, Operational effectiveness, Environment) and Comments
		1	2	3	4	5	6	7	8	9	10		
WO-SHORE-22321	DEFECT - REQUEST R/A TO REPLACE STBD SHAFT RPM GAUGE WIRING TO STBD ENGINE ROOM - SHE-PIR-2201-016-D0252545										x	Un-executable due to SMF degradation	
WO-SHORE-42290	RE-CONNECT/REPLACE PORT & STBD RUT TANK LEVEL INDICATORS - FUEL AND OIL SYSTEMS										x	Un-executable due to SMF degradation	
WO-SHORE-52537	DEFECT - RA TO TUNE STBD ME AND PROVIDE SATS SUPPORT										x	Un-executable due to SMF degradation	
WO-SHORE-52536	DEFECT - RA TO TUNE PORT ME AND PROVIDE SATS SUPPORT										x	Un-executable due to SMF degradation	
WO-SHORE-61687	SHN-PIR2301-008 - ADD 20 - REPLACE HYDRAULIC MOTORS										x	Un-executable due to SMF degradation	
WO-SHORE-62071	SHN-PIR-2301-015/016 - ADD 25 - REPLACE/REPAIR GAUGES & METERS										x	Un-executable due to SMF degradation	
WO-SHORE-38034	DEFECT - DEEP CLEAN OF VESSEL AFTER DOCKING - SLIPPING										x	Encapsulation preventing completion of task	
WO-SHORE-21694	DEFECT - REQUEST RA TO REPLACE VIDEO CABLES										x	Encapsulation preventing completion of task	
WO-SHORE-48591	HIDRR - SHEP-210011 PAINT FRACTURES - GALLEY EPOXY DECK COATING										x	Encapsulation preventing completion of task	
WO-SHORE-40350	DEFECT - CONDUCT GROOM OF THE TDFLS SYSTEM AFTER 24M WEAMS PMS										x	Requires Air conditioning systems to be operational to complete	
WO-SHORE-58370	ADD 05 - RECTIFY TDFLS FAULT										x	Requires Air conditioning systems to be operational to complete	
WO-SHORE-36611-1	SHN-PIR-2301-001 - FAULT FIND TSSS LOW IMPEDANCE FAULT										x	HSS tasks halted under HSPD direction	
WO-SHORE-42289	REVERSE OSMOSIS - CHEMICAL CLEAN PIPEWORK REVERSE OSMOSIS UNIT										x	HSS tasks halted under HSPD direction	
WO-SHORE-42288	DEFECT - PROVIDE DE-STORING / STORING SUPPORT FOR DOCKING										x	HSS tasks halted under HSPD direction	

Legend:

10 - Other

Navy Systems Removed From Vessel