

External Preventative Maintenance jobs either not taken on, not completed, were deferred or cancelled during the maintenance availability

Job Number	Job Title	Reason for deferral or non-completion (See legend below)										Additional comments	Risk Assessment (Safety, Operational effectiveness, Environment) and
		1	2	3	4	5	6	7	8	9	10		
WO-SHORE-36607	PMS 3648 - ELM 12 MONTHLY PERFORMANCE MONITORING SYSTEM SENSOR CHECKS - CYCLE 2										X	IDENTIFIED AS BEING UN- EXECUTABLE DUE TO SMF DEGRADATION	
WO-SHORE-39412	PMS 3648 - ELM 12 MONTHLY PERFORMANCE MONITORING SYSTEM SENSOR CHECKS - CYCLE 3										X	IDENTIFIED AS BEING UN- EXECUTABLE DUE TO SMF DEGRADATION	
WO-SHORE-38162	PMS 6656 - 12 MONTHLY - NOBEL K-5 FIRE EXTINGUISHING SYSTEM										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-36619	PMS6215 ELM6M - INSPECT AIR CONDITIONING SUB-SYSTEMS										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-2108	PMS S6004C 2.5YR.1-2 GALLEY DUCTING: CONDUCT 2.5 YEARLY ROUTINES										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-37041	PMS S6030O DL.1 VENTILATION SUPPLY TRUNKING SYSTEM: CHEMICAL CLEAN INTERNAL AREA										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-2111	PMS6215 ELM24M - SERVICE AIR CONDITIONING FCU - CYCLE 3										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-2052	PMS6215 ELM96M - OVERHAUL AIR CONDITIONING SUB-SYSTEM										X	ENCAPSULATION PREVENTING COMPLETION OF TASK	
WO-SHORE-2086	PMS6274 ELM 24M WEMS REFURBISHMENT										X	REQUIRES AIRCONDITIONING SYSTEMS TO BE OPERATIONAL TO COMPLETE	
WO-SHORE-36612	PMS6374 ELM 6M INSPECT AND LUBRICATE TDPLS-DS										X	REQUIRES AIRCONDITIONING SYSTEMS TO BE OPERATIONAL TO COMPLETE	
WO-SHORE-37045	PMS 6169-30 MONTHLY-SEWAGE TREATMENT PLANT- OMNIPURE										X	REQUIRES AIRCONDITIONING SYSTEMS TO BE OPERATIONAL TO COMPLETE	
WO-SHORE-36618	PMS3607 ELM4M.3 CLEANING UNDER WATER SENSORS										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-37067	PMS3607 ELM 12M.7 - REMOVE AND REPLACE SVP-70										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-2148	PMS3607 ELM 24M.5 - REMOVE AND REPLACE MBES TRANSDUCERS AND RECEIVER										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-36610	PMS3607 ELM4M.1 SMLHSS INSPECT GPS ANTENNA CONNECTIONS AND MOUNTINGS										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-36620	PMS3609 ELM 3M 1T06 INSP. CLN BATTERY OF FFCPT, INSP MVP SYS AND RPL SSFF SENS0										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-36608	PMS3607 ELM4M.1 SMLHSS SOFTWARE MAINTENANCE										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-36611	PMS3608 ELM 6M 1T06 INSP EXTRNAL AND INTRNAL CONNECTION, WINCH DRIVE SYS TS55-DC										X	HSS TASKS HALTED UNDER HSPO DIRECTION	
WO-SHORE-36604	6M SERVICE AND TDS PROBE RECALIBRATION - PMS7631										X	HSS TASKS HALTED UNDER HSPO DIRECTION	

Legend:

10 - Other

Navy Systems Removed From Vessel